Work Ord Thursday, June													Page 1	
Item ID: Revision ID:	D3272-1				Accept						Setup	Start		
Item Name:	Step											Stop		
Start Date: Required Date: Reference:	6/30/2011 7/7/2011	Start Qu Req'd Q	ty: 8.00 ety: 8.00	) (2000)   1841   1861   1861	1881	Ą	Cust Ite							
Approvals:	Process Pla	ın:	H	Date: //- 6(c	-3C Tooling: SPC (Y/N):			Date:	_ 		Run	Start Stop		
Sequence ID/ Work Center II		Operation Descript			Set Up/ Run Hours	•	Tool I	D Tool#	Plan Code	Accept Qty	Rej Qty	-	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr										.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
D3272	Rev	В												
100 Large Fab		Large Fab			0.00									
Large Fab			1-Cut D262		E CUTTING OTHER END** 6.25" long as per Dwg D3272	-	utting	Refil		8		ø	1,	1.07.0
*		•	2-Drill extr 3-Deburr	usion as per Dwg D32	72 using Jig DT8680 for rivet	S.							٠.	

Quality Control

QC6- Inspect dimensions to drawing

Memo

Λ

<b>Dart Aerospace Ltd</b>	space Ltd	art Aeros
---------------------------	-----------	-----------

	•								£ > #
W/O:			WC	ORK ORDER CHANG	ES				<u> </u>
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		-				,			
		•	·					·	
Part No		PAR #:	Fault Cate	gory:	_ NCR: Yes I	No DQ	A:	Date:	
Resolution:			Dispositio	n:	sed:		Date: _		
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC		on B	ation	Approval	Approval		
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
								,	
						-			
							!		

## Work Order ID 71395

Thursday, June 30, 2011 12:47:10 PM



Page 2

Item ID:

D3272-1

Setup Start

Stop



**Revision ID:** 

Item Name: Step

Required Date: 7/7/2011

6/30/2011

Start Qty: 8.00

Req'd Qty: 8.00



**Cust Item ID:** 

**Customer:** 

Tool ID

Reference:

**Start Date:** 

An	provals:	
wh	pi uvais.	

Process Plan:

Date:

**Tooling:** 

Date:

Run

Reject

Qty

SPC (Y/N):

Set Up/

Date:

Stop

Reject

Number Stamp

Insp.

Sequence ID/ **Work Center ID** 

120

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: WA-

Date:

**Run Hours** 

0.00

0.00

1/11.07.08

Tool # Plan

Code

Accept

Qty

130

Quality Control

QC21- Final Inspection - Work Order Release

Memo

Memo

0.00

0.00

M17111 TC MF 11-07-08

Accept

		<del></del>							<b>(</b>
W/O:		100000	WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:		
<u> </u>									
Part No	•	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date: _	
Resolution:		solution:	Disposition	:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC		tion B		cation	Approval	Approval	
DAIL		Section A	Initial Action Des Chief Eng Chief E		Sign Date		tion C	Chief Eng	QC inspector
						1.			

### **Picklist Print**

Thursday, June 30, 2011 12:47:17 PM

Work Order ID: 71395

Parent Item:

D3272-1

Parent Item Name: Step



Start Date: 6/30/2011

Required Date: 7/7/2011

Start Qty: 8.00

Required Qty: 8.00

**Comments:** 

IPP Rev:A

New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No			100	Each	145.7000	1	8 ///	<i>e</i> (		
										14	11.07	.08	

Step Extrusion

<b>Location</b>	Loc Qty	Loc Code
HALL	132	
64409	6	
68293	126	
WA	13.7	
46910	2	
66970	11.7	



	•								€ ,
W/O:		,	W	ORK ORDER CHANG	BES	-	•		
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							! :		
			A. The Section 1						
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	Date:	
Resolu		esolution:	on: Disposition:					Date: _	
NCR:		,	WORK OR	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	1		tion B		cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		on C	Chief Eng	QC Inspector



		- 1		
DESIG	"A	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAL	
CHEC	SED	APPROVED	DRAWING NO.	REV. B
(	E	# <u></u>	D3272	SHEET 1 OF 3
DATE			TITLE	SCALE
07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

OT OF OF

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

#### **GENERAL NOTES:**

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 7/375

M11-04-30

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


_									
W/O:			WC	RK ORDER CHANGE	ES				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
:									
				•					
Part No		PAR #:	Fault Cate	norv:	NCR: Ye	s No DO	)Δ.	Date:	
		esolution:							
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NO	CR)			
DATE	STEP	Description of NC Section A	Corrective Action Initial Action Descri Chief Eng Chief Eng		n B Sigi	1&r∣ <sub>Se</sub>	ication	Approval Chief Eng	Approval QC Inspector
			Offici Eng	One Eng	Ja	ie .			



W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								:		
							·			
•		· · · · · · · · · · · · · · · · · · ·								
Part No	:	PAR #:	Fault Cate	egory:	NCF	: Yes I	No DQ	A:	_ Date: _	·····
	Resolution: Disposition:					N/C Clo	sed:		Date:	
NCR:		V	WORK ORE	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			ction B	Cian 0	Verification		Approval	Approval
DAIL	OIL.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
•										
								•		







Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	- copace -									
W/O:			WO	RK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE			В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		``	·							
			÷				- 10			
Part No:		PAR #:	Fault Categ	NCR: Yes No DQA: _			A:	Date:		
	Res	solution:	Disposition	_ QA: N	C Clo	sed:	Date:			
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (I	NCR)				
DATE	STEP	Description of NC	Corrective Action Section			ν		cation	Approval	Approval
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Secti		Chief Eng	QC inspector
						¥.,			-	
									,	
				/			<u> </u>			
		`				1				
	<u>.</u>	•								
		· · · · · · · · · · · · · · · · · · ·								
			,							
i,								*		
	1 1	•	3 1							1

NOTE: Date & initial all entries